



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
May 16, 2009

Reviewed: R

Mine Name: Goldstrike Mine	Permit Number: M/053/0005
Operator Name: USMX Utah, Inc.	Inspection Date: October 29, 2008
Inspector(s): Lynn Kunzler	Time: noon
Other Participants: Russell Shriener, BLM	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

Revegetation efforts have been very successful, with vegetation cover far exceeding the revegetation standard. The area showed no signs of accelerated erosion. During this inspection, the Wildlife guzzlers that were installed were inspected. There was little evidence that they were being utilized much. While the rancher in the area indicated he had removed his cows from the area, there were over 17 cows observed within the reclaimed area. Russ Shriener indicated he would pass this on to the BLM range con.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Continue to monitor this site when in the area.

Inspector's Signature _____

O:\M053-Washington\M0530005-Goldstrike\inspections\Insp-10292008.doc